



ASSEMBLY INSTRUCTION








GIFFORD DINING TABLE




ROWICO

H O M E



1x1 	2x4 	Ax8  M8x60	Bx8  Ø8
Cx8  Ø8/Ø16	D  N5	Ex4  Ø40x2	

 Improper use, improper assembly and mishandling may lead to defects/ cracks appearing.

